
RENAULT

TRAFIC VAN


(2014 -)









2.



4.





	Airbag		Gas generator		Seat belt pretensioner
	Low voltage battery		Gas strut / pre-loaded spring		High resistance zone
	Fuel tank		SRS control unit		Area requiring special attention

1. Identification / recognition



2. Immobilization / stabilization / lifting

Immobilization




Engine stop




3. Disable direct hazards / safety regulations

12 Volt battery





Engine stop
Disconnect the (-) 12V batteries





4. Access to the occupants






Presence of bilateral reinforcements under the centre console

STEERING COLUMN:
hollow, fragile at the wheel






Laminated glass

Tempered glass

REINFORCED STEELS





5. Stored energy / liquids / gases / solids

	80 L	Possible seat movements Reinforced steel


6. In case of fire

GAS SPRINGS





Risk of missile effect of cylinders




7. In case of submersion





No electrical risk

10. Explanation of pictograms used

	Vehicle running on Group 1 liquid fuel				
	Move the hands-free key away		hood		
	Flammable		Dangerous for human health		Environmental hazard